

audison

| bit

BIT ONE SOFTWARE AND AC-LINK DRIVER INSTALLATION ON WINDOWS 8, 8.1 and 10


Rev.C




ideato,
progettato,
costruito
in Italia


Bit One software and AC-Link driver installation on Windows 8, 8.1 and 10

REMARK: The following procedure will temporary disable Windows driver signature enforcement, to allow the AC-Link drivers installation. The driver signature enforcement will be enabled again with the next reboot. The procedure has to be performed only once: after the AC-Link driver installation is completed, it is NOT necessary to repeat this procedure again every time you want to connect and use the bit One.


1. Install the bit One PC software by double-clicking on the Setup.exe file which you can find in the bit One Setup CD. Follow and complete the installation wizard.
2. Copy the AC-Link Driver v1_1 folder enclosed in this package to the PC Desktop (or wherever you prefer).
3. Press and keep pressed down the Windows key on the keyboard (it is located at the bottom left side, look for the  symbol). Then, press the R key.




4. The following dialogue window will appear:



5. ype shutdown.exe /r /o /f /t 00 in the "Open" field and click on "OK":




6. The following screen will be shown. Click on "Troubleshoot":




7. The following screen will be shown.
Click on "Advanced options":




8. The following screen will be shown.
Click on "Startup Settings":




9. The following screen will be shown.
Click on "Restart".




10. The PC will reboot. The following screen will be shown during reboot. Press "7" (Disable driver signature enforcement) and wait for complete Windows startup.



- 11. WIN 8, 8.1:** Right-click on the Windows Start screen. "**All apps**" key will show on the bottom right angle of the screen. Click it:
WIN 10: Click on the Windows Start screen. Locate "**Settings**" and click on it:




Windows 8, 8.1




Windows 10

- 12. WIN 8, 8.1:** The screen will show all the icons. Locate the "**Control Panel**" icon and click on it:
WIN 10: Locate the "**Devices**" icon and click on it:




Windows 8, 8.1




Windows 10

13. WIN 8, 8.1: The Control Panel will show up. Click on **"Hardware and Sound"**:

WIN 10: The Device menu will show up. Click on **"Connected devices"**:




Windows 8, 8.1




Windows 10

14. WIN 8, 8.1: Click on **"Device Manager"**:

WIN 10: Click on **"Device Manager"**:





Windows 8, 8.1




Windows 10

15. Power on the bit One processor and connect the USB to the PC.


16. The Control Panel will show the **"AC-Link interface"** with an exclamation mark.
Double click on **"AC-Link interface"**:




17. The following dialogue window will be shown.
Click on "Update Driver..."




18. Click on "Browse my computer for driver software":




19. Browse for the AC-Link Driver v1_1 previously copied as per step nr. 2 of this guide, and click on "OK"




20. Click on "Next":




21. The following warning will showup, this is normal. Click on "Install this driver software anyway":




22. The AC-Link interface driver is now installed. The AC-Link Port still has to be installed. Click on "Close" to close the dialogue windows:




23. The system will now find the AC-Link port, named **"USB Serial Port"** as shown in the following screen. Double-click on "USB Serial Port":




24. Click on "Update driver...":




25. Click on "Browse my computer for driver software":




26. The system will propose the previously used AC-Link Drivers v1_1 folder: if so, click on "Next". Otherwise, click on "Browse..." locate the AC-Link Drivers v1_1 folder and then click on "Next":




27. The following warning will show up, this is normal. Click on "Install this driver software anyway":



28. The AC-Link port driver is now installed, and the driver installation procedure is complete. Click on "Close" to close the dialogue windows:



29. The bit One is now ready to use: double-click on the "bit One" icon as usual.





All specifications subject to change without notice

www.audison.eu

audison
ISTINTO
INNOVATIVO

PART OF ELETTRONEDIA
62018 Potenza Picena (MC) Italy
T +39 0733 870 870 - F +39 0733 870 880
www.elettromedia.it